Oil Field Environmental Incident Summary

Date/Time of Notice: 05/17/2014 19:35 Incident: 20140517193537 Responsible Party: OXY USA INC. Well Operator: OXY USA INC. Well Name: DELVIN DUKART 4-30-31H-143-95 Field Name: MANNING Well File #: 27372 Date Incident: 5/16/2014 Time Incident: 23:00 Facility ID Number: DUNN Twp: 143 **Rna**: 95 **Sec:** 19 **Qtr:** County: Location Description: Submitted By: Terry Ryland Received By: Contact Person: Terry Ryland 5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 1 Mile Distance Nearest Occupied Building: Distance Nearest Water Well: Type of Incident: Tank Overflow Release Contained in Dike: Yes - On Facility Site Reported to NRC: No **Units** Spilled Recovered Units Followup **Units** Oil **Brine Barrels** Barrels barrels Other **Description of Other Released Contaminant:** Inspected: Written Report Received: 1/21/2016 Clean Up Concluded: 5/17/2014 Risk Evaluation:

Tuesday, January 24, 2017 Page 1 of 3

Minor

Areal Extent:

Potential Environmental Impacts:

Surface soil only

Action Taken or Planned:

Trican notified WSM and safety. Vac Truck onsite was used to sucked up residuals

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 5/19/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a tank overflow was not contained. Followup is necessary.

Date: 5/29/2014 Status: Correspondence Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I inspected the site and did not see any discharge off pad. I contacted personnel from the company. They indicated that the produced water that overflowed didn't come from the frac tank but from the frac company's mixing unit just south of the frac tanks labeled as working tanks. No water ran off of site; that area actually had a depression due to traffic and rain prior to the frac. No further followup is required at this time.

Date: 5/29/2014 **Status:** Awaiting Documentation **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Waiting on more inforamtion regarding the spill; could not tell were it occurred on pad.